

CYLINDER INSPECTION REPORT

MFO NUMBER: T377-ENF-101-AY
DRAWING NUMBER: 322124
REVISION NUMBER: A
READ THICKNESS: MIN 3.23 MAX 3.73

NCIR#: _____
INSPECTOR: Kyle Leach
CUSTOMER: ENFA Cylinder
DATE: 1/22/2019
READ O.D.: MIN _____ MAX _____

POUR LOCATION: _____

TOP THICKNESS/ID

3.570 A

MIDDLE THICKNESS/ID




3.546 A

CYLINDER INSPECTION: Thickness


Top ☐ Bottom ☐

BOTTOM THICKNESS/ID

3.556 A



OD: _____



COMMENTS: _____